

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B4



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B4



Photo 3 North approach from center of structure



Photo 4 South approach from center of structure

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B4




Photo 5 East elevation



Photo 6 West elevation

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B4



Photo 7 Loose gravel, tire rutting & potholes at ends of deck on approach wearing surface



Photo 8 Hazard sign leaning away from roadway on NE corner of deck

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B4



Photo 9 Rot, checks and splits on timber curb along west edge of deck




Photo 10 Weathering on timber girders



Photo 11 Moderate honeycombing and scaling noted on NW wingwall




Photo 12 Moderate scaling on base of north abutment wall

Structure Condition Summary Form

Structure Name Pautois Bridge
Structure Number B5
Date of Inspection August 9, 2024
Project No.
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Abutment	Abutment Walls	Sq.m	900.00	60.90	0.00	60.90	0.00	0.00	54810	41108	75	00	00
	Ballast Walls	Sq.m	350.00	16.70	0.00	16.70	0.00	0.00	5845	4384	75	00	00
	Bearings	Each	1000.00	8.00	0.00	7.00	1.00	0.00	8000	5650	71	00	00
Approaches	Wingwalls	Sq.m	350.00	24.32	0.00	24.32	0.00	0.00	8512	6384	75	00	00
	Approach Slabs	Sq.m	140.00	94.80	0.00	94.80	0.00	0.00	13272	9954	75	00	00
	Wearing Surface	Sq.m	6.00	94.80	0.00	90.80	2.00	2.00	569	413	73	00	15, 02
Barriers	Railing Systems	m	200.00	36.96	0.00	36.86	0.10	0.00	7392	5537	75	00	00
	Girders -Steel	Sq.m	420.00	151.62	0.00	151.62	0.00	0.00	63680	47760	75	00	00
Coatings	Structural steel	Sq.m	80.00	36.80	0.00	35.80	1.00	0.00	2944	2180	74	00	00
	Deck Top - Thin Slab	Sq.m	120.00	160.78	0.00	160.78	0.00	0.00	19294	14470	75	00	00
Decks	Soffit - Thin Slab	Sq.m	120.00	172.97	0.00	172.97	0.00	0.00	20756	15567	75	00	00
	Wearing Surface	Sq.m	25.00	133.06	0.00	125.06	4.00	4.00	3327	2385	72	00	15

Bridge Condition Index (BCI)	75	208401	155792
------------------------------	----	--------	--------

I _t	Importance Factor for Traffic	0
I _e	Importance Factor for Economic Impacts	0
I _w	Importance Factor for Bridge Width	0
I _p	Importance Factor for Bridge Profile or Alignment	0

Bridge Sufficiency Index (BSI)	75
--------------------------------	----

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

INVENTORY DATA:

Structure Name	Pautois Bridge		
Main Hwy/Road #	Peddlers Drive	Under Structure:	Navigable Water <input type="checkbox"/> Non- Navigable Water <input checked="" type="checkbox"/>
		Rail <input type="checkbox"/> Road <input type="checkbox"/> Pedestrian <input type="checkbox"/> Other <input type="checkbox"/>	
Road Name:	Peddlers Drive	On Structure:	Rail <input type="checkbox"/> Road <input checked="" type="checkbox"/> Pedestrian <input type="checkbox"/> Other <input type="checkbox"/>
Structure Location	0.34 km west of Pautois Rd.		
Latitude	46° 15 '37.3 " N	Longitude	78° 50' 53.60" W
Owner(s)	Township of Calvin	Heritage Designation	Not Cons. <input checked="" type="checkbox"/> Cons. /Not App. <input type="checkbox"/> List/Not Desig. <input type="checkbox"/>
			Desig./not List <input type="checkbox"/> Desig. & List <input type="checkbox"/>
MTO Region	-	Road Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input type="checkbox"/>
MTO District	-	Posted Speed	- No. of Lanes 2
Old County	-	AADT	- % Trucks -
Geographic Twp.	-	Special Routes	Transit <input type="checkbox"/> Truck <input type="checkbox"/> School <input type="checkbox"/> Bicycle <input type="checkbox"/>
Structure Type	Steel Girder Bridge	Detour Length Around Structure	- (km)
Total Deck Length	18.48 (m)	Fill on Structure	- (m)
Overall Str. Width	8.7 (m)	Skew Angle	- (Degrees)
Total Deck Area	160.78 (m ²)	Direction of Structure	East/West
Roadway Width	7.9 (m)	No. of Spans	1
Span Lengths	18.48 (m)		

HISTORICAL DATA

Year Built	2012	Last OSIM Inspection	May 30, 2022
Year of Last Major Rehab.	-	Last Enhanced OSIM Inspection	-
Current Load Limit	- (tonnes)	Last Bridge Master Inspection	-
Load Limit By-Law #	-	Last Evaluation	-
By-Law Expiry Date	-	Last Underwater Inspection	-
Min. Vertical Clearance	- (m)	Last Condition Survey	-

Rehabilitation History: (Date / Description)

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

FIELD INSPECTION INFORMATION	
Date of Inspection:	August 9, 2024
Inspector:	Tashi Dwivedi, P.Eng., HP Engineering
Others in Party:	Derick Battrick, P.Eng., HP Engineering
Access Equipment Used:	Measuring Tape, Digital Camera and Hammer
Weather:	Sun and Cloud
Temperature:	23 °C
Type of Inspection: <input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM	

ADDITIONAL INVESTIGATION REQUIRED	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study:	X			\$ -
Material Condition Survey	X			\$ -
Detailed Deck Condition Survey:	X			\$ -
Non-destructive Delamination Survey of Asphalt- Covered Deck:	X			\$ -
Concrete Substructure Condition Survey:	X			\$ -
Detailed Coating Condition Survey:	X			\$ -
Detailed Timber Investigation:	X			\$ -
Underwater Investigation:	X			\$ -
Fatigue Investigation:	X			\$ -
Seismic Investigation:	X			\$ -
Structure Evaluation:	X			\$ -
Monitoring	X			\$ -
Monitoring of Deformations, Settlement and Movements:	X			\$ -
Monitoring Crack Widths:	X			\$ -
Load Posting – Estimated Load Limit				\$ -
			Total Cost	\$ -
Investigation Notes:				

OVERALL STRUCTURAL NOTES:	
Recommended Work on Structure:	<input checked="" type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments:	
Overall, structure is generally in good condition. Wide transverse cracks at ends of approach slabs and medium to wide longitudinal cracks along both approach centrelines. Minor loss of stone noted at embankments on west with exposed geotextile.	
Date of Next Inspection:	May 2026

Suspected Performance Deficiencies

- 00 None
- 01 Load carrying capacity
- 02 Excessive deformations (deflections & rotation)
- 03 Continuing settlement
- 04 Continuing movements
- 05 Seized bearings

Maintenance Needs

- 01 Lift and swing bridge maintenance
- 02 Bridge cleaning
- 03 Bridge handrail maintenance
- 04 Painting steel bridge structures
- 05 Bridge deck joint repair
- 06 Bridge bearing maintenance

- 06 Bearing not uniformly loaded/unstable
- 07 Jammed expansion joint
- 08 Pedestrian/vehicular hazard
- 09 Rough riding surface
- 10 Surface ponding
- 11 Deck drainage

- 07 Repair of structural steel
- 08 Repair of bridge concrete
- 09 Repair of bridge timber
- 10 Bailey bridges maintenance
- 11 Animal/pest control
- 12 Bridge surface repair

- 12 Slippery surfaces
- 13 Flooding/channel blockage
- 14 Undermining of foundation
- 15 Unstable embankments
- 16 Other

- 13 Erosion control at bridges
- 14 Concrete sealing
- 15 Rout and seal
- 16 Bridge deck drainage
- 17 Scaling (loose Concrete or ACR Steel)
- 18 Other

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Approaches		Length:	30 m	
Element Name:	Barrier		Width:	-	
Location:	East & West Approaches		Height:	-	
Material:	Steel		Count:	4	
Element Type:	Steel Flex Beam on Steel Posts		Total Quantity:	120 m	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	Hot Dip Galvanizing				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m	-	120	-	-
Comments: Generally in good condition. Some minor abrasions observed.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Approaches		Length:	6 m	
Element Name:	Wearing Surface		Width:	7.9 m	
Location:	East & West		Height:	-	
Material:	Asphalt		Count:	2	
Element Type:	Approach Wearing Surface		Total Quantity:	94.8 m ²	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	90.8	2	2
Comments: Generally in good condition with wide transverse cracks at ends of approach slabs and wide longitudinal cracks along the both approach centrelines. Wide longitudinal crack noted on west approach. Light ravelling throughout the approach on both sides. Accumulation of sand on edges of roadway.					
Performance Deficiencies: 00			Maintenance Needs: 15, 02		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Approaches		Length:	6 m	
Element Name:	Approach Slabs		Width:	7.9 m	
Location:	East & West of Structure		Height:	0.25 m	
Material:	Concrete		Count:	2	
Element Type:	Concrete Approach Slab		Total Quantity:	94.8 m ²	
Environment:	Moderate		Limited Inspection:	<input checked="" type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	94.8	-	-
Comments: Based on the condition of wearing surface, the approach slabs are estimated assumed to be in good condition.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Accessories		Length:	-	
Element Name:	Signs		Width:	-	
Location:	NE, NW, SE & SW of Structure		Height:	-	
Material:	Steel		Count:	4	
Element Type:	Hazard Signs (Steel)		Total Quantity:	4	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	-	4	-	-
Comments: Hazards signs are generally in good condition with minor deformation and abrasion noted.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Barriers		Length:	18.48 m	
Element Name:	Railing Systems		Width:	-	
Location:	North & South of Sides of Structure		Height:	-	
Material:	Steel		Count:	2	
Element Type:	HSS Rails on Steel Posts		Total Quantity:	36.96 m	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	Hot Dip Galvanizing				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m	-	36.86	0.1	-
Comments: Generally in good condition with minor abrasion noted at south barrier.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Decks		Length:	18.48 m	
Element Name:	Wearing Surface		Width:	7.2 m	
Location:	Top of Deck		Height:	-	
Material:	Asphalt		Count:	1	
Element Type:	Deck Wearing Surface		Total Quantity:	133.06 m ²	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	125.06	4	4
Comments: Generally in good condition with light asphalt polishing and light ravelling noted throughout. Medium longitudinal crack observed at centerline.					
Performance Deficiencies: 00			Maintenance Needs: 15		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Decks		Length:	18.48 m	
Element Name:	Deck Top (Covered)		Width:	8.7 m	
Location:	Top of Deck		Height:	-	
Material:	Concrete		Count:	1	
Element Type:	Thin Slab		Total Quantity:	160.78 m ²	
Environment:	Moderate		Limited Inspection:	<input checked="" type="checkbox"/>	
Protection System	Asphalt Wearing Surface				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	160.78	-	-
Comments: Based on the condition of wearing surface, the visible edges of the deck top and the soffit, the deck top is estimated to be in good condition.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Decks		Length:	18.48 m	
Element Name:	Soffit – Thin Slab (Exterior)		Width:	0.93 m	
Location:	North & South Underside of Structure		Height:	-	
Material:	Concrete		Count:	2	
Element Type:	Thin Slab		Total Quantity:	34.37 m ²	
Environment:	Moderate		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²		34.37	-	-
Comments: Soffit exterior is generally in good condition.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Decks		Length:	18.48 m	
Element Name:	Soffit – Thin Slab (Interior)		Width:	7.5 m	
Location:	Underside of Structure		Height:	-	
Material:	Concrete		Count:	1	
Element Type:	Thin Slab		Total Quantity:	138.6 m ²	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	138.6	-	-
Comments: Soffit interior is generally in good condition with hairline longitudinal cracks noted.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Beams / MLEs		Length:	2 m	
Element Name:	Girders (End)		Width:	0.3 m	
Location:	East & West Underside of Deck		Height:	0.7 m	
Material:	Steel		Count:	8	
Element Type:	Steel I-Girders		Total Quantity:	36.8 m ²	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	Paint				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	36.8	-	-
Comments: Ends of steel girders are in good condition; coating is noted.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Beams / MLEs		Length:	12.48 m	
Element Name:	Girders (Intermediate)		Width:	0.3 m	
Location:	Underside of Deck		Height:	0.7 m	
Material:	Steel		Count:	4	
Element Type:	Steel I-Girders		Total Quantity:	114.82 m ²	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	114.82	-	-
Comments: Intermediate steel girders are in good condition.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Beams / MLEs		Length:	2.5 m	
Element Name:	Diaphragms (Ends)		Width:	0.09 m	
Location:	East & West Underside of Structure		Height:	0.38 m	
Material:	Steel		Count:	6	
Element Type:	Steel C-Channels		Total Quantity:	6	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	Paint				
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	-	6	-	-
Comments: Steel diaphragms in end region are in good condition; coating is noted.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Beams / MLEs		Length:	2.5 m	
Element Name:	Diaphragms (Intermediate)		Width:	0.09 m	
Location:	Underside of Structure		Height:	0.38 m	
Material:	Steel		Count:	6	
Element Type:	Steel C-Channels		Total Quantity:	6	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	-	6	-	-
Comments: Intermediate steel diaphragms are in good condition.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Coatings		Length:	2 m	
Element Name:	Structural Steel (End)		Width:	0.3 m	
Location:	Coating on Girders (End)		Height:	0.7 m	
Material:	Concrete		Count:	8	
Element Type:	Paint		Total Quantity:	36.8 m ²	
Environment:	Moderate		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	34.8	2	-
Comments: Coating on end portions of girders is in good condition with some light flaking and local failure.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Coatings	Length:	2.5 m		
Element Name:	Structural Steel (End)	Width:	0.09 m		
Location:	Coating on Diaphragms (End)	Height:	0.38 m		
Material:	Concrete	Count:	6		
Element Type:	Paint	Total Quantity:	6		
Environment:	Moderate	Limited Inspection:	<input type="checkbox"/>		
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	6	-	-
Comments: Coating of diaphragms in end regions is in good condition					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Abutments	Length:	4 m		
Element Name:	Wingwalls	Width:	-		
Location:	NE, NW, SE & SW of Structure	Height:	1.52 m		
Material:	Concrete	Count:	4		
Element Type:	Reinforced Concrete Wingwall	Total Quantity:	24.32 m ²		
Environment:	Moderate	Limited Inspection:	<input type="checkbox"/>		
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	24.32	-	-
Comments: Wingwalls are in good condition. Moss growth noted at deck interface on neoprene pad.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Abutments		Length:	-	
Element Name:	Ballast Walls		Width:	8.7 m	
Location:	East & West Underside of Structure		Height:	0.96 m	
Material:	Concrete		Count:	2	
Element Type:	Reinforced Concrete Ballast Wall		Total Quantity:	16.70 m ²	
Environment:	Benign		Limited Inspection:	<input checked="" type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	16.7	-	-
Comments: Ballast walls are generally in good condition based on partially visible portions. Damp stains observed on East ballast wall.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Abutments		Length:	-	
Element Name:	Bearings		Width:	-	
Location:	On Abutment Wall		Height:	-	
Material:	Neoprene / Rubber		Count:	8	
Element Type:	Elastomeric Bearing		Total Quantity:	8	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	-	7	1	-
Comments: Abutment bearings are in good condition. Steel shoe plates at each bearing location are in good condition as well. Minor deformation of steel plate at northeast bearing.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Abutments		Length:	-	
Element Name:	Abutment Walls		Width:	8.7 m	
Location:	East & West Underside of Structure		Height:	3.5 m	
Material:	Concrete		Count:	2	
Element Type:	Reinforced Concrete Abutment		Total Quantity:	60.9 m ²	
Environment:	Benign		Limited Inspection:	<input checked="" type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	60.9	-	-
Comments: Abutment walls are partially covered by slope protection. Visible portions are in good condition.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Foundations		Length:	-	
Element Name:	Foundation (Below Ground Level)		Width:	-	
Location:	Below Abutment Walls		Height:	-	
Material:	Concrete		Count:	-	
Element Type:	Unknown		Total Quantity:	-	
Environment:	Benign		Limited Inspection:	<input checked="" type="checkbox"/>	
Protection System	Unknown				
Condition Data:	Units	Excellent	Good	Fair	Poor
	N/A	-	-	-	-
Comments: No visible evidence of foundation instability observed at time of inspection.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Embankments and Streams	Length:	-		
Element Name:	Embankments	Width:	-		
Location:	NE, NW, SE & SW of Structure	Height:	-		
Material:	Native Soil	Count:	6		
Element Type:	Embankment	Total Quantity:	6		
Environment:	Moderate	Limited Inspection:	<input type="checkbox"/>		
Protection System	Rock Protection				
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	-	5	1	-
Comments: Embankments appear stable, they are moderately sloped and covered by rock slope protection. Minor loss of stone noted at west with exposed geotextile.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Embankments and Streams	Length:	-		
Element Name:	Slope Protection	Width:	-		
Location:	NE, NW, SE & SW of Structure	Height:	-		
Material:	Rock	Count:	6		
Element Type:	Rock Slope Protection	Total Quantity:	6		
Environment:	Moderate	Limited Inspection:	<input type="checkbox"/>		
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	-	5	1	-
Comments: Slope protection is generally in good condition with some loss of slope protection at west.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

ELEMENT DATA					
Element Group:	Embankments and Streams		Length:	-	
Element Name:	Streams and Waterways		Width:	-	
Location:	Below Main Span		Height:	-	
Material:	Native		Count:	-	
Element Type:	Streams		Total Quantity:	All	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	All	-	All	-	-
Comments: Moderate volume with high flow from south to north with no visible flow obstructions at time of inspection.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B5

REPAIR AND REHABILITATION REQUIRED		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6 - 10 Years	1 - 5 Years	< 1 year	
Total Cost					\$

ASSOCIATED WORK	Comments	Estimated Cost
Approaches		
Detours		
Traffic Control		
Utilities		
Right of Way		
Environmental Study		
Other		
Contingencies		
Total Cost		\$ -

JUSTIFICATION

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B5



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B5



Photo 3 East approach from center of structure



Photo 4 West approach from center of structure

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B5



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B5



Photo 7 Wide transverse and longitudinal cracks on west approach wearing surface



Photo 8 Accumulation of dirt and debris below approach guide rail

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B5



Photo 9 Wide longitudinal center-line crack on deck wearing surface



Photo 10 Hazard sign at SW approach is leaning and has minor dents and abrasions

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B5



Photo 11 Minor deformation and light corrosion on steel bearing plate, NE bearing



Photo 12 Localized coating failure (delamination) on girder ends

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.:B5



Photo 13 Typical underside of structure (girders, diaphragms, and soffit)



Photo 14 Damp staining on exterior soffit and wingwall SE corner of structure

Structure Condition Summary Form

Structure Name Crosses Bridge
Structure Number B6
Date of Inspection August 9, 2024
Project No.
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Abutment Walls	Sq.m	900.00	49.40	0.00	48.40	1.00	0.00	44460	33030	74	00	00
	Wingwalls	Sq.m	350.00	28.94	0.00	24.44	3.00	1.50	10129	6836	67	00	08
	Wearing Surface	Sq.m	6.00	102.00	0.00	91.00	10.00	1.00	612	434	71	00	18
Barriers	Railing Systems	m	200.00	37.20	0.00	0.00	18.60	18.60	7440	1488	20	08	18
	Deck Top - Thick Slab	Sq.m	350.00	80.00	0.00	80.00	0.00	0.00	28000	21000	75	00	00
	Soffit - Thick Slab	Sq.m	350.00	88.00	0.00	81.50	5.00	1.50	30800	22094	72	00	08
Decks	Wearing Surface	Sq.m	25.00	68.00	0.00	68.00	0.00	0.00	1700	1275	75	00	00
										123141	86156		

Bridge Condition Index (BCI) 70

I_t Importance Factor for Traffic 0
I_e Importance Factor for Economic Impacts 0
I_w Importance Factor for Bridge Width 0
I_p Importance Factor for Bridge Profile or Alignment 0

Bridge Sufficiency Index (BSI) 70

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

INVENTORY DATA:

Structure Name	<u>Crosses Bridge</u>		
Main Hwy/Road #	<u>Homestead Road</u>	Under Structure:	Navigable Water <input type="checkbox"/> Non- Navigable Water <input checked="" type="checkbox"/>
		Rail <input type="checkbox"/> Road <input type="checkbox"/> Pedestrian <input type="checkbox"/> Other <input type="checkbox"/>	
Road Name:	<u>Homestead Road</u>	On Structure:	Rail <input type="checkbox"/> Road <input checked="" type="checkbox"/> Pedestrian <input type="checkbox"/> Other <input type="checkbox"/>
Structure Location	<u>1.21 km west of Daventry Road</u>		
Latitude	<u>46° 14' 29.6" N</u>	Longitude	<u>78° 50' 51.1" W</u>
Owner(s)	<u>Township of Calvin</u>	Heritage Designation	Not Cons. <input checked="" type="checkbox"/> Cons. /Not App. <input type="checkbox"/> List/Not Desig. <input type="checkbox"/>
		Desig./not List <input type="checkbox"/> Desig. & List <input type="checkbox"/>	
MTO Region	<u>-</u>	Road Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input type="checkbox"/>
MTO District	<u>-</u>	Posted Speed	<u>-</u> No. of Lanes <u>2</u>
Old County	<u>-</u>	AADT	<u>-</u> % Trucks <u>-</u>
Geographic Twp.	<u>-</u>	Special Routes	Transit <input type="checkbox"/> Truck <input type="checkbox"/> School <input type="checkbox"/> Bicycle <input type="checkbox"/>
Structure Type	<u>Concrete Rigid Frame</u>	Detour Length Around Structure	<u>-</u> (km)
Total Deck Length	<u>8</u> (m)	Fill on Structure	<u>-</u> (m)
Overall Str. Width	<u>10</u> (m)	Skew Angle	<u>-</u> (Degrees)
Total Deck Area	<u>80</u> (m ²)	Direction of Structure	<u>East/West</u>
Roadway Width	<u>8.5</u> (m)	No. of Spans	<u>1</u>
Span Lengths	<u>8</u> (m)		

HISTORICAL DATA

Year Built	<u>1983</u>	Last OSIM Inspection	<u>May 30, 2022</u>
Year of Last Major Rehab.	<u>-</u>	Last Enhanced OSIM Inspection	<u>-</u>
Current Load Limit	<u>-</u> (tonnes)	Last Bridge Master Inspection	<u>-</u>
Load Limit By-Law #	<u>-</u>	Last Evaluation	<u>-</u>
By-Law Expiry Date	<u>-</u>	Last Underwater Inspection	<u>-</u>
Min. Vertical Clearance	<u>-</u> (m)	Last Condition Survey	<u>-</u>

Rehabilitation History: (Date / Description)

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

FIELD INSPECTION INFORMATION	
Date of Inspection:	August 9, 2024
Inspector:	Tashi Dwivedi, P.Eng., HP Engineering
Others in Party:	Derick Battrick, P.Eng., HP Engineering
Access Equipment Used:	Measuring Tape, Digital Camera and Hammer
Weather:	Overcast
Temperature:	23 °C
Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM

ADDITIONAL INVESTIGATION REQUIRED	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study:		X		\$ 5,000.00
Material Condition Survey	X			\$ -
Detailed Deck Condition Survey:		X		\$ 10,000.00
Non-destructive Delamination Survey of Asphalt- Covered Deck:	X			\$ -
Concrete Substructure Condition Survey:	X			\$ -
Detailed Coating Condition Survey:	X			\$ -
Detailed Timber Investigation:	X			\$ -
Underwater Investigation:	X			\$ -
Fatigue Investigation:	X			\$ -
Seismic Investigation:	X			\$ -
Structure Evaluation:	X			\$ -
Monitoring	X			\$ -
Monitoring of Deformations, Settlement and Movements:	X			\$ -
Monitoring Crack Widths:	X			\$ -
Load Posting – Estimated Load Limit			Total Cost	\$ 15,000.00
Investigation Notes: Rehabilitation/replacement study is for traffic barrier only. A detailed deck condition survey is recommended due to the vintage of structure and condition of deck.				

OVERALL STRUCTURAL NOTES:	
Recommended Work on Structure:	<input type="checkbox"/> None <input checked="" type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments: Structure is generally in good condition. Adequacy of existing traffic barrier should be verified. End treatments are substandard and should be replaced with code compliant end treatments. Potholes on wearing surface should be filled. Wide horizontal crack observed on half the length on north fascia. Medium to wide horizontal crack full length with some localized delamination and efflorescence noted on south fascia.	
Date of Next Inspection:	June 2026

Suspected Performance Deficiencies

- 00 None
- 01 Load carrying capacity
- 02 Excessive deformations (deflections & rotation)
- 03 Continuing settlement
- 04 Continuing movements
- 05 Seized bearings

Maintenance Needs

- 01 Lift and swing bridge maintenance
- 02 Bridge cleaning
- 03 Bridge handrail maintenance
- 04 Painting steel bridge structures
- 05 Bridge deck joint repair
- 06 Bridge bearing maintenance

- 06 Bearing not uniformly loaded/unstable
- 07 Jammed expansion joint
- 08 Pedestrian/vehicular hazard
- 09 Rough riding surface
- 10 Surface ponding
- 11 Deck drainage

- 07 Repair of structural steel
- 08 Repair of bridge concrete
- 09 Repair of bridge timber
- 10 Bailey bridges maintenance
- 11 Animal/pest control
- 12 Bridge surface repair

- 12 Slippery surfaces
- 13 Flooding/channel blockage
- 14 Undermining of foundation
- 15 Unstable embankments
- 16 Other
- 13 Erosion control at bridges
- 14 Concrete sealing
- 15 Rout and seal
- 16 Bridge deck drainage
- 17 Scaling (loose Concrete or ACR Steel)
- 18 Other

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

ELEMENT DATA					
Element Group:	Approaches		Length:	NE 7.2m, NW 11.5m, SE 8.2m, SW 11.2m	
Element Name:	Barrier		Width:	-	
Location:	East & West Approaches		Height:	-	
Material:	Steel		Count:	4	
Element Type:	Steel Flex Beam on Wood Posts		Total Quantity:	38 m	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	Hot Dip Galvanizing				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m	-	-	19	19
Comments: Abrasions observed throughout north and south guide rail. Rot and weathering noted throughout wooden posts. End treatments are substandard and should be replaced with code compliant end treatments. End treatments at northwest and southwest approaches are installed beyond the shoulder rounding.					
Performance Deficiencies: 08 – Pedestrian/Vehicular Hazard			Maintenance Needs: 18 – Replace Damaged Rail Sections / Rotten Posts		
Recommended Work: <input type="checkbox"/> Rehab. <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Approaches		Length:	6 m	
Element Name:	Wearing Surface		Width:	8.5 m	
Location:	East & West		Height:	-	
Material:	Gravel		Count:	2	
Element Type:	Gravel Wearing Surface		Total Quantity:	102 m ²	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	91	10	1
Comments: Generally in good condition. Moderate vegetation growth in front of approach guiderail. Bump formed at west end of deck, east bound lane. Loose gravel noted on approaches.					
Performance Deficiencies: 00			Maintenance Needs: 18 – Clear Vegetation, patch pothole		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

ELEMENT DATA					
Element Group:	Accessories		Length:	-	
Element Name:	Signs		Width:	-	
Location:	Ends of Approach Guiderail		Height:	-	
Material:	Plastic		Count:	4	
Element Type:	White Plastic Markers		Total Quantity:	4	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	-	3	-	1
Comments: Generally in good condition. The markers appear to have been placed to mark the end of the approach guardrail as a hazard. Official hazard signs are recommended. Southeast markers have fallen over.					
Performance Deficiencies: 00			Maintenance Needs: 18- Install New hazard signs		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Barriers		Length:	18.6 m	
Element Name:	Railing Systems		Width:	-	
Location:	North & South of Sides of Structure		Height:	-	
Material:	Steel		Count:	2	
Element Type:	Steel Flex Beam on Wood Posts		Total Quantity:	37.2 m	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	Hot Dip Galvanizing				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m	-	-	18.6	18.6
Comments: Minor dents and abrasions on the steel flex beam with some cracks and deterioration of grout pads. Wood posts exhibit rot and weathering. Adequacy of existing traffic barrier should be reviewed. Some grout pads covered in debris.					
Performance Deficiencies: 08			Maintenance Needs: 18- Clear debris		
Recommended Work: <input type="checkbox"/> Rehab. <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

ELEMENT DATA					
Element Group:	Decks		Length:	8 m	
Element Name:	Wearing Surface		Width:	8.5 m	
Location:	Top of Deck		Height:	-	
Material:	Gravel		Count:	1	
Element Type:	Gravel Wearing Surface		Total Quantity:	68 m ²	
Environment:	Severe		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	68	-	-
Comments: Wearing surface is generally in good condition.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Decks		Length:	8 m	
Element Name:	Deck Top (Covered)		Width:	10 m	
Location:	Top of Deck		Height:	-	
Material:	Concrete		Count:	1	
Element Type:	Thick Slab		Total Quantity:	80 m ²	
Environment:	Moderate		Limited Inspection:	<input checked="" type="checkbox"/>	
Protection System	Gravel Wearing Surface				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	80	-	-
Comments: Based on the condition of the wearing surface and the underside of the deck, the deck top is assumed to be in good condition. Narrow longitudinal cracks observed on exposed edges of deck.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

ELEMENT DATA					
Element Group:	Decks		Length:	8 m	
Element Name:	Soffit – Thick Slab (Exterior)		Width:	1 m	
Location:	North & South Underside of Structure		Height:	0.5 m	
Material:	Concrete		Count:	2	
Element Type:	Thick Slab		Total Quantity:	24 m ²	
Environment:	Moderate		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	17.5	5	1.5
Comments: Wide horizontal crack observed on half the length on north fascia. Medium to wide horizontal crack full length with some localized delamination and efflorescence noted on south fascia. Efflorescence, rust and damp stains noted. Narrow longitudinal cracks with efflorescence on north and south underside of the exterior soffit.					
Performance Deficiencies: 00			Maintenance Needs: 08		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years		

Element Group:	Decks		Length:	8 m	
Element Name:	Soffit – Thick Slab (Interior)		Width:	8 m	
Location:	Underside of Structure		Height:	0.5 m	
Material:	Concrete		Count:	1	
Element Type:	Thick Slab		Total Quantity:	64 m ²	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	64	-	-
Comments: Generally in good condition.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

ELEMENT DATA					
Element Group:	Abutments		Length:	-	
Element Name:	Wingwalls		Width:	5.4 m	
Location:	NE, NW, SE & SW of Structure		Height:	1.34 m	
Material:	Concrete		Count:	4	
Element Type:	Reinforced Concrete Wingwall		Total Quantity:	28.94 m ²	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	24.44	3	1.5
Comments: Generally in good condition with narrow map cracks, localized delamination, damp stains and efflorescence. Heavy efflorescence observed at southwest wingwall.					
Performance Deficiencies: 00			Maintenance Needs: 08		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years		

Element Group:	Abutments		Length:	2.47 m	
Element Name:	Abutment Walls		Width:	10 m	
Location:	East & West Underside of Structure		Height:	-	
Material:	Concrete		Count:	2	
Element Type:	Reinforced Concrete Abutment		Total Quantity:	49.4 m ²	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m ²	-	48.4	1	-
Comments: Generally in good condition with a small medium crack, damp stains and efflorescence at the top of the south end of the west abutment wall. Narrow vertical cracks and efflorescence noted throughout.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

ELEMENT DATA					
Element Group:	Foundations	Length:	-		
Element Name:	Foundation (Below Ground Level)	Width:	-		
Location:	Below Abutment Walls	Height:	-		
Material:	Concrete	Count:	-		
Element Type:	Strip Footing	Total Quantity:	-		
Environment:	Benign	Limited Inspection:	<input checked="" type="checkbox"/>		
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	N/A	-	-	-	-
Comments: No visible evidence of foundation instability at the time of inspection.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

Element Group:	Embankments and Streams	Length:	-		
Element Name:	Embankments	Width:	-		
Location:	NE, NW, SE & SW of Structure	Height:	-		
Material:	Native Soil	Count:	4		
Element Type:	Embankment	Total Quantity:	4		
Environment:	Moderate	Limited Inspection:	<input type="checkbox"/>		
Protection System	Slope Protection				
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	-	4	-	-
Comments: Generally in good condition with a few large stones at base of embankments. Embankments are moderately sloped, well vegetated, and appear stable.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

ELEMENT DATA					
Element Group:	Embankments and Streams		Length:	-	
Element Name:	Slope Protection		Width:	-	
Location:	NE, NW, SE & SW of Structure		Height:	-	
Material:	Rock		Count:	4	
Element Type:	Rock Protection		Total Quantity:	4	
Environment:	Moderate		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	All	-	-	4	-
Comments: Slope protection is in generally fair condition. Slope protection consists of a few large stones positioned at the base of embankments. Addition of small stones to prevent erosion around the large stone that are present.					
Performance Deficiencies: 00			Maintenance Needs: 18 - Reinstate Slope Protection		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years		

Element Group:	Embankments and Streams		Length:	-	
Element Name:	Streams and Waterways		Width:	-	
Location:	Below Structure		Height:	-	
Material:	Native		Count:	-	
Element Type:	Streams		Total Quantity:	All	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	All	-	All	-	-
Comments: High volume, low flow from south to north with no visible flow obstructions noted at the time of inspection.					
Performance Deficiencies: 00			Maintenance Needs: 00		
Recommended Work: <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 – 5 Years <input type="checkbox"/> 6 – 10 Years			Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years		

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

Site No.: B6

REPAIR AND REHABILITATION REQUIRED		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6 - 10 Years	1 - 5 Years	< 1 year	
Approach Barrier	Install new approach guiderail and approved end treatments			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost					\$ 48,000.00

ASSOCIATED WORK	Comments	Estimated Cost
Approaches		
Detours		
Traffic Control		
Utilities		
Right of Way		
Environmental Study		
Other		
Contingencies		
Total Cost		\$ -

JUSTIFICATION

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.: B6



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.: B6



Photo 3 East approach from center of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.: B6



Photo 5 North elevation




Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.: B6



Photo 7 Substandard end treatment at south east approach barrier



Photo 8 Deformed steel beam deck barrier on north edge of deck

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.: B6



Photo 9 Dents, abrasions, and substandard end treatment on NW approach guide rail



Photo 10 Wide horizontal cracks and isolated concrete delamination on north soffit exterior

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.: B6



Photo 11 Horizontal and vertical cracks with efflorescence and small spall on SW wingwall



Photo 12 Wide horizontal cracks with efflorescence on south exterior soffit

MUNICIPAL STRUCTURE INSPECTION FORM

BRIDGE

SITE PHOTOGRAPHS

Site No.: B6




Photo 13 Light scaling on deck soffit



Photo 14 Narrow map cracks on SE wingwall

